



Photograph of building damage from 1906 San Francisco, CA earthquake by G.K. Gilbert. Courtesy of the U.S.G.S. Photographic Library (libraryphoto.cr.usgs.gov/).



Photograph of chimney damage from 1886 Charleston, SC earthquake by J.K. Hillers. Courtesy of the U.S.G.S. Photographic Library (libraryphoto.cr.usgs.gov/).






FIGURE 46.— Isoseismal map for the New York City, New York, earthquake of August 10, 1884. Isoseismals are based on intensity estimates from data listed in references 369, 463, 518, and 529 of table 1.